

## Unadilla River at Rockdale, New York

<b>Latitude:</b>	<b>Longitude:</b>	<b>Gauge Elevation:</b>	<b>Drainage Area:</b>	<b>County of Gauge:</b>	<b>County of Town:</b>	<b>Minor_Mod_Maj:</b>
42°22'40"	75°24'22"	992.25 feet	520 mi2	Chenango, NY	Chenango, NY	11.0_12.0_13.0

### Top Five Lowest Stages

Period of Record - 1939 to September 30, 2016

Date	Crest (ft)	Flow (cfs)	Remarks
9/26/1939	3.10	missing	Also occurred 9/25/1939
8/14/1965	3.20	missing	none
9/6/1999	3.24	missing	Also occurred 9/5/1999
9/2/1966	3.40	missing	none
9/20/2001	3.43	missing	Also occurred 8/11/1997 and 9/17 - 18/1997 and 9/28 - 29/1997 and 10/19 - 23/1997

### Additional Low Stage Information

Date	Crest (ft)	Flow (cfs)	Remarks
9/29/2015	4.00	72	Also occurred 9/27 - 28/2015

### Additional Remarks

Low water records are somewhat limited. Therefore some low stages could be missing. Our low stage listing includes valid and sometimes questionable stages. In some cases we have a brief list of questionable stages since it was unclear if the readings were due to a gauge malfunction or there wasn't enough data to determine its validity. Low stage (if found) are listed if there hasn't been any low stages in the last 15 years. The USGS sometime tweak their readings so please contact the USGS if you need more information.